

BOXER

2-4

3-6

99730-10

GEZE

3 mm

4 mm

5 mm

2x

2x

2x

4x

4x

1

2

20,7

12

30

3

4 mm

2x

M8x14

4

3 mm

1-2 Nm

5

5 mm

7-8,5 Nm

7-8,5 Nm

6

45°

45°

7

4x

5x20

4x

M5x14

8

2x

4,5x30







2x

M5x14




9

7-8,5 Nm


12





		K [mm]
	0	8,5
	+4	12,5
	+8	16,5




		K [mm]
	0	8,5
	+4	12,5
	+8	16,5



() = Boxer 3-6



() = Boxer 3-6



Tel.: 0049 7152 203 0
Fax: 0049 7152 203 310
www.geze.com



GEZE