





TS 5000 L

030172-13



GEZE





5 mm

A


B


















$a \leq 1400 \text{ mm}$



$a \leq 1400 \text{ mm}$




X	G
≤ 90	140
> 90	150
≤ 100	150





4x
M5x45


1




2




3




4




5




6




7



8



9



i

