




TS 1500

101827-10



GEZE




10 mm

A




$a \leq 1100 \text{ mm}$




B




$a \leq 1100 \text{ mm}$




EN 3/4














EN 2




EN 3/4





EN 2





1



2




3




4

a = 950 - 1100 mm (EN 4)




a < 950 mm (EN 3)

a < 850 mm (EN 2)




a = 950 - 1100 mm (EN 4)




a < 950 mm (EN 3)



a < 850 mm (EN 2)





5





6





7




8






i




EN 3/4




EN 2




EN 3/4



EN 2



EN 3/4



EN 2

